



FIGURE 1









FIGURE 4



Cause editor Cause Editor \boxtimes -61Name: Toner cartridge 62 -Subcause of: Probability: 23.3645 **Explanation** Categories Dataflow This cause is a consumable (toner cartridge, fuser, transfer roller or feed and separation rollers). 67 ~ →□ Automatic data collection possible. 68 ~ ☐ Can be fixed by rebooting the PC. ─□ Can be fixed by power cycling the printer. Printer 78 Dependency of environment: Operating system Printer driver Network Paper handling devices Name of cause given to customers: 79 Delete cause OK Cancel

FIGURE 6

60 -

77

Cause probability editor




FIGURE 7

Cause category editor






FIGURE 8



Extra information editor for actions



Action probability editor

Probability of action	\boxtimes	
Assuming that Transfer roller]	
is the only cause of Leading edge scatter]	
what is the probability that correctly performing the step		
Perform user maintenance will solve the problem?		
100 OK Cancel		~ 110

FIGURE 11

General question editor




FIGURE 12

Probability change editor





FIGURE 13

. 100 m



Cause editor for actions and questions




FIGURE 15






FIGURE 16